

KOMATSU PC200-10	
MAKER:	KOMATSU
MODEL:	PC200-10
SERIAL NO.:	4548**
YEAR:	2016YR
HOURLY:	17597Hrs
SPEC:	KOMATSU 454888 2016yr 17597hr
LOCATION:	YOKOHAMA
PLATE NO.:	N/A
STAMP:	N/A

CONDITION

Ref No: JMX11199

Detail	Details
Engine	Grade: C - Oil Leak (Engine head cover oil seepage), Fuel Leak (Engine fuel hose deteriorated)
Radiator	Grade: C
Operation	Grade: C
Swing Device	Grade: C - Swing Circle/Swivel Joint(Swing circle seal missing), Free description(Swing circle grease supply tube damaged)
Travel	Grade: C
Boom Cylinder	Grade: C - Boom cylinder (left) oil seepage, Boom cylinder rod (left) scratched, Boom cylinder (right) oil seepage,Boom cylinder rod (right) scratched
Arm Cylinder	Grade: C - Arm cylinder oil seepage, Arm cylinder rod scratched
Bucket Cylinder	Grade: C - Bucket cylinder oil seepage, Bucket cylinder rod scratched
Hydraulic Pump	Grade: C - Main pump suction hose oil seepage
Control Valve	Grade: C - Control valve oil seepage

COMMENTS:

Work Unit: Boom (Boom foot excessive play, Boom middle repair mark) Arm: (Arm tip deformed, Arm foot excessive play) Bucket (front attachment, etc): (Bucket wear,Bucket excessive play)

JAMEX CO., LTD.

English: We are not responsible for the accuracy of this inspection information or the actual condition of the machine.

Japanese: この査定情報の正確性および実際の機械の状態について、当社は責任を負いません。

Generated on: 2026-10-06 10:20:10

Machine ID: JMX11199