

HITACHI ZX225US-3	
MAKER:	HITACHI
MODEL:	ZX225US-3
SERIAL NO.:	2159**
YEAR:	2010YR
HOUR:	7474Hrs
SPEC:	* Oil leak at the bucket cylinder * Play/looseness at the bucket mounting point * A/C malfunction (no cold air)
LOCATION:	HAKATA
PLATE NO.:	N/A
STAMP:	N/A

CONDITION

Ref No: JMX11719

Detail	Details
Engine	Grade: C
Radiator	Grade: C
Operation	Grade: C
Swing Device	Grade: C
Travel	Grade: C

COMMENTS:

* Oil leak at the bucket cylinder * Play/looseness at the bucket mounting point * A/C malfunction (no cold air)

JAMEX CO., LTD.

English: We are not responsible for the accuracy of this inspection information or the actual condition of the machine.

Japanese: この査定情報の正確性および実際の機械の状態について、当社は責任を負いません。