

KOMATSU WA100-3	
YEAR:	2002YR
HOUR:	Hrs
SPEC:	KOMATSU WA100-3 Yr 2002 Hr 56130 CNP
SHOE:	N/A
LOCATION:	YOKOHAMA
PLATE NO.:	N/A
STAMP:	N/A

ENGINE

Maker:	N/A
Model:	N/A
S/No.:	N/A
EXHAUST GAS REGULATIONS:	N/A

CONDITION

Ref No: JMX9983

Detail	Details
Engine Radiator	Grade: C - Blow-by [Slight]
Swing Device	Grade: C
Operation	Grade: C - Fuse: Corrosion (see photos)
Travel	Grade: C - Forward/Backward lever: Stiff. Sometimes the vehicle may not move due to corrosion of the fuse box.
Exterior Body	Grade: C - Articulated hinge: Play & Loose [Severe] Right-lift cylinder: Oil leak [Moderate] Bucket-pin: Play & Loose [Moderate] Left-lift cylinder: Oil leak [Slight]

COMMENTS:

No additional comments.

JAMEX CO., LTD.

English: This inspection information is for reference only. It is not to guarantee the condition of the actual machine. For more information, visit our website at www.jamex.co.jp

Japanese: この査定情報はあくまで参考資料であり、実際の機械の状態を保証するものではありません。詳細については、当社ウェブサイト www.jamex.co.jp をご覧ください。

Generated on: 2026-07-21 22:44:26

Machine ID: JMX9983